



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: August 11, 2006

Supervisor 1027

Mine Name: Quarry Antone
Operator Name: Utah Portland Cement

Permit number: M0450021
Inspection Date: 08/09/2006
Time:

Inspector(s): Dan Smith
Other Participants: None
Mine Status: INA

Weather:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:
Site visit while checking on S0450058.


Directions to Site:
Easy access from paved Grantville road.

Inspection Summary:
Site shows no signs of recent activity. Vegetation is taking over road access and perimeter of site.

Conclusions and Recommendations:
Recommend that the primary inspector review this mine and also S0450058.

Inspector's Signature Daniel Smith Date: August 11, 2006

ds
cc: Operator
(Agency)
Attachment: Map & Photos



State of Utah
Division of Oil Gas & Mining
Mining/Exploration Summary

08/07/2006

SMALL MINING OPERATION

Permt #

S450058

Name:

FALENIA MINE

Permit Status

Status: **APP** Approved:
Recieved: **09/24/2001** **10/09/2001**
Tent Appr: / /

Mine Status

Status: **INA**
Date: **01/01/2002**

Ownership

Surface: **FEE**
Mineral: **FEE**

Location

UTMX: **368,334**
UTMY: **4,500,470**

MethodsMinerals Mined/Explored: **CLAY**Surf/Under: **SURFACE**

Methods Used:

Bonding

Approved Acres	Acres Released	Date Released
5	0	/ /
Bond Type		
N/A		
Bond Amount:	Date Bond Expires:	
\$ 0	/ /	

Permit Fees

Date Sent	Date Received
06/23/2006	07/13/2006
Fee Received	Cash Receipt
\$ 150	72000000007
Delinquent Notice	
/ /	

Comments:

1/31/2006 - Rec'd 2005 annual report. No production, no new or reclaimed acres.

2/7/2005 - Received 2004 annual report. No activity took place. No current plan at the present time, but hope to mine from the area in the future.

2/2/2004 - Received 2003 annual report. No activity. No current plans for any activity at the present time. Would like to pursue mining if get permission from mineral and/or surface owner.

3/11/2003 - Received letter stating that on or about April 1, 2003, Pacific Coast Building Products currently doing business as Interstate Brick Company will reorganize from a single corporate entity to a parent company that wholly owns a group of subsidiary companies,

Last ActionAction: **05 FEE**Start Date: **06/28/2005**End Date: **07/19/2005**

Fee \$150 - Receipt # 6NROG000005

Last Inspection

Date / /

Inspector

Last Annual Report 2005Acreage: **1.0**Acr Reclaimed: **0.0**Production: **0, ,****Last Agency Action**

Agency:

Agency ID:

Date: / /

Operator INTERSTATE BRICK COMPANY

Oper Id:

420


TaxID

94-610-3555Contact: **JOHN HEWITT**Address: **9780 S 5200 W**Phone: **(801) 280-5200**Fax **(801) 280-5220 /****WEST JORDAN UT 84088**E-Mail **john.hewitt@paccoast.com**

10/31/2005 - Any legal documents for Interstate Brick Company MUST be addressed as PABCO Building Products, LLC dba Interstate Brick

Location

Qqqtr	Qqtr	Qtr	Section	Township	Range	Merid	Quad	Sheet
		NW	17	S02.0	W06.0	S	flux	utah



Mine Number: M0450021
Mine Name: Quarry Antone
Township 02 S Range 08 W Section 17, 18 SLBM

Inspection Date Aug. 09, 2006
Map Produced by DKS

Acres Disturbed	11.61
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0.37


Total Acres Disturbed	11.98
-----------------------	-------

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- | | |
|-----------------|---|
| County Boundary | Township or range Line |
| Access | Township or range line: location doubtful |
| Mine | Section line |
| NonMine | Section line: location doubtful |
| Reclaimed | Disturbed |
| Other | Regraded |
| Interstate | Seeded |
| US Route | Released |
| State Route | Excluded |
| Primary Route | PreExisting |
| Secondary Route | Prelaw |
| Main Dirt Road | Bond Area |
| Unimproved Road | SITLA Mineral Leases |
| Interchange | BLMSalableMinerals |
| Trail | CommunityPit |
| | SITLA Mineral Ownership |

DOQ imagery date 2004



0 625

Feet
1:7,500 1 inch equals 625 feet
Verify Scale

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.